



EXHIBIT C



EXPLANATION

- Shallow groundwater monitoring well (corrective action)
- Shallow groundwater monitoring well (detection monitoring)
- ⊙ Deep groundwater monitoring well
- ▲ Surface water sampling location
- (23.53) Groundwater or surface water elevation (Ft.-MSL); measured October 5-13, 2010
- (<23.3) Indicates well was dry. Elevation shown is bottom of casing.
- ? — 20 — Groundwater elevation contour (Ft.-MSL)
- ← Approximate direction of groundwater flow
- ▨ Approximate extent of groundwater impacted by VOCs



DATE 3/23/10
 DWN KMM
 APP TLV
 REV 0
 PROJECT NO. 053-7465

FIGURE 1
 LOS OSOS LANDFILL
 SAN LUIS OBISPO COUNTY, CALIFORNIA
 IMPACTED GROUNDWATER
 ESTIMATED EXTEND OF

Dimscale: 1 Ltscale: 1 Plotscale: 1=1
 G:\053-7465\FIGURES\IMPACTED GW AREA\DWG 3/26/11

Topographic base map from Golden State Aerial Surveys. 3/12/04.